

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/04/2024

Submitted Date:

01/17/2025

Document Number:

714300180

**FIELD INSPECTION FORM**

Loc ID 406271 Inspector Name: Brown, Kari On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
All Inspections		cogcc@kpk.com	
Graber, Nikki		nikki.graber@state.co.us	
Collins, Kilian		kilian.collins@state.co.us	
Norton, Matthew		mnorton@kpk.com	
Watzman, Ross		rwatzman@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456076	SPILL OR RELEASE	CL	11/26/2018		-	Crude Tank Leak	EI

**General Comment:**

ECMC environmental inspection to determine progress on Spill ID 456076/Remediation 12110. Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Incident information:**

Spill Discovery Date: 7/12/2018  
Days since spill discovery: 2,337 days  
Last report: 7/18/2024

**Current site status:**

Excavation has been backfilled. Only one monitoring well was observed on location; destroyed monitoring well located adjacent to present monitoring well has not been properly abandoned. All tanks have been removed from location but piping remains. Small unmarked soil stockpiles present on location with no BMPs (stockpiles appear to be clean soil). Weeds present throughout location.

**Inspected Facilities**

Facility ID: 456076 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714300181	Insp Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6880785">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6880785</a>