

Inspection Photos
Location Name: QB Energy ALP 19-10 (K19NE) Pad
Location #: 335338



Photo # 8572 From entrance to location



Photo # 8573 From entrance to location

Inspection Photos
Location Name: QB Energy ALP 19-10 (K19NE) Pad
Location #: 335338




Photo # 8574 Location



Photo # 8575 Location

Inspection Photos
Location Name: QB Energy ALP 19-10 (K19NE) Pad
Location #: 335338



Photo # 8576 Location



Photo # 8577 Location

Inspection Photos
Location Name: QB Energy ALP 19-10 (K19NE) Pad
Location #: 335338



Photo # 8578 Location



Photo # 8579 Location

Inspection Photos
Location Name: QB Energy ALP 19-10 (K19NE) Pad
Location #: 335338



Photo # 8580 Location



Photo # 8581 Location

Inspection Photos

Location Name: QB Energy ALP 19-10 (K19NE) Pad

Location #: 335338




Photo # 8582 Location



**Photo # 8583 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**



Inspection Photos
Location Name: QB Energy ALP 19-10 (K19NE) Pad
Location #: 335338



**Photo # 8584 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**



Photo # 8585 Wire fence needs maintenance

Inspection Photos
Location Name: QB Energy ALP 19-10 (K19NE) Pad
Location #: 335338



**Photo # 8586 Poly pipe along lease road open ended
/wildlife hazard/available for entry by wildlife**



**Photo # 8587 Poly pipe along lease road open ended
/wildlife hazard/available for entry by wildlife**

Inspection Photos

Location Name: QB Energy ALP 19-10 (K19NE) Pad

Location #: 335338



Photo # 8588 API # on ALP 19-9 wellhead sign incorrect



Photo # 8589 No FORM 4 SUNDRY for equipment/not in compliance with CECMC rules

Inspection Photos

Location Name: QB Energy ALP 19-10 (K19NE) Pad

Location #: 335338



**Photo # 8590 ALP 19-9 bradenhead line tied into separator
/failure to comply with COA's**



**Photo # 8591 ALP 19-9 bradenhead line tied into separator
/failure to comply with COA's**



Inspection Photos

Location Name: QB Energy ALP 19-10 (K19NE) Pad

Location #: 335338



**Photo # 8592 ALP 19-9 bradenhead line tied into separator
/failure to comply with COA's**



**Photo # 8593 ALP 19-9 bradenhead line tied into separator
/failure to comply with COA's**

