

**Inspection Photos**  
**Location Name: Champlin HER 2-8 OWP**  
**Location ID: 320245**



**Pic 1 separator**



**Pic 2 Tanks**

**Inspection Photos**  
**Location Name: Champlin HER 2-8 OWP**  
**Location ID: 320245**



**Pic 3 Oil tank overflowed**



**Pic 4 GMR, Separator**



**Inspection Photos**  
**Location Name: Champlin HER 2-8 OWP**  
**Location ID: 320245**



**Pic 5 pumpjack / wellhead**



**Pic 6 Wellhead sign**



**Inspection Photos**  
**Location Name: Champlin HER 2-8 OWP**  
**Location ID: 320245**



**Pic 7 Pit**