

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/10/2025

Submitted Date:

01/10/2025

Document Number:

696307124

**FIELD INSPECTION FORM**
 Loc ID 472549 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

ECMC Operator Number: 10661

Name of Operator: CIVITAS NORTH LLC

Address: 555 17TH STREET #3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
472545	WELL	PR	06/24/2021	OW	123-50829	Big Mountain Viper Fed 8-59 16-17-18-2	PR
472549	LOCATION	AC			-	Big Mountain Viper 8-59 16	AC
472550	WELL	PR	06/24/2021	OW	123-50833	Big Mountain Viper 8-59 16-17-18-5	PR
472551	WELL	PR	06/24/2021	OW	123-50834	Big Mountain Viper Fed 8-59 16-17-18-1	PR
472553	WELL	PR	12/01/2023	OW	123-50836	Big Mountain Viper Fed 8-59 16-17-18-3	PR
472554	WELL	PR	12/01/2023	OW	123-50837	Big Mountain Viper 8-59 16-17-18-7	PR
472555	WELL	PR	06/24/2021	OW	123-50838	Big Mountain Viper Fed 8-59 16-17-18-4	PR
472556	WELL	PR	06/24/2021	OW	123-50839	Big Mountain Viper 8-59 16-17-18-6	PR

**General Comment:**

This is a Well PAD and Production Facility Field Compliance Audit

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency Contact Name and Number is NOT current. All Wellhead Signs, Tank Labels, and Sign at Entrance STILL show the previous Operator's Contact Name and Number; no Civitas North Contact Number is present on the entire Location.

Corrective Action: Comply with Rule 605. All 24 HOUR BISON CONTACT PHONE NUMBERS on ALL Signs on Location need to be covered up or Changed. Bison Oil & Gas II does not own or operate this Location/Wells any longer.

Date: 01/17/2025

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			

Corrective Action:		Date:	
Type: Emission Control Device	# 5		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Instrumental Air Units		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	750 BBLS
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:		Shares berm with the Crude Oil Tanks					
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	6	OTHER	STEEL AST		40.661310,-103.989600		
Comment:							
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
<b>Venting:</b>							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
<b>Flaring:</b>							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities									
Facility ID:	472545	Type:	WELL	API Number:	123-50829	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	472549	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	AC
<b>Producing Well</b>									
Comment:	PR - Active Production Facility								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	472550	Type:	WELL	API Number:	123-50833	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	472551	Type:	WELL	API Number:	123-50834	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	472553	Type:	WELL	API Number:	123-50836	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	472554	Type:	WELL	API Number:	123-50837	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	472555	Type:	WELL	API Number:	123-50838	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	472556	Type:	WELL	API Number:	123-50839	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
Routine Field Compliance Audit	petrie	01/10/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404055132	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6872806">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6872806</a>
696307125	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6872796">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6872796</a>