

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/16/2025

Submitted Date:

01/19/2025

Document Number:

707603572

FIELD INSPECTION FORM

Loc ID 451045 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

20 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451046	WELL	PR	05/01/2024	OW	123-44948	Wells Ranch State BB09-617	PR
451047	WELL	PR	05/01/2024	OW	123-44949	Wells Ranch BB11-627	PR
451048	WELL	PR	05/01/2024	OW	123-44950	Wells Ranch BB11-618	PR
451050	WELL	PR	05/01/2024	OW	123-44951	Wells Ranch BB11-635	PR
451051	WELL	PR	05/01/2024	OW	123-44952	Wells Ranch BB09-639	PR
451052	WELL	PR	05/01/2024	OW	123-44953	Wells Ranch BB09-626	PR

General Comment:

This is a WELL inspection.
Well(s): 6: Producing | PR.
Battery: Active.

Centralized Battery serves 3 Location IDs
(451073, 451060, 451045).
(Well(s): 17: Producing | PR; 1: Shut-In |SI).

Centralized Battery serves 1 Tank Battery Facility ID
(480940).

- Reference:
- A.) Field Inspection Report doc. #707603568 and/or Location ID #451073 for PR Well(s) info.
 - B.) Field Inspection Report doc. #707603570 and/or Location ID #451060 for PR, SI Well(s) info.
 - C.) Field Inspection Report doc. #707603572 and/or Location ID #451045 for PR Well(s) info.
 - D.) Field Inspection Report doc. #707603574 and/or Facility ID #480940 for Battery / Facility, Equipment info.

Location

Lease Road:			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
	Comment: 6: Wellsite(s).		
Corrective Action:			Date:
	Type CONTAINERS		
	Comment: Wellsite(s): Corrosion Inhibitor, Methanol (Placards).		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type WELLHEAD		
	Comment: 6: Wellsite(s). Iron panel.		
Corrective Action:			Date:
	Type OTHER		
	Comment: Gaslift Injection meters / headers: Iron pipe.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Other	# 6		
	Comment: 6: Wellsite(s). Gas lift injection lines.		
Corrective Action:			Date:
Type: Plunger Lift	# 6		
	Comment: 6: Wellsite(s).		
Corrective Action:			Date:
Type: Gas Meter Run	# 6		

Comment:	Wellsite(s): 6: Gas Lift Allocation; (Chevron). Calibration card(s) indicates calibration <= 1 year. Last calibration: 08/24/2024.		
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:	6: Wellsite(s). Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 6		
Comment:	Wellsite(s): 1: Bradenhead pressure mitigation device. 2: Corrosion Inhibitor pump(s), tank(s) w/ drip containment. 3: Methanol pump(s), tank(s) w/ drip containment.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.416167,-104.411952
Comment:	Centralized Battery serves 3 Location IDs (451073, 451060, 451045). (Well(s): 17: Producing PR; 1: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (480940).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 451046 Type: WELL API Number: 123-44948 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/24/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451047 Type: WELL API Number: 123-44949 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/28/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451048 Type: WELL API Number: 123-44950 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/08/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451050 Type: WELL API Number: 123-44951 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/29/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451051 Type: WELL API Number: 123-44952 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 386 Fluid Type: NONE
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451052 Type: WELL API Number: 123-44953 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/08/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: _____
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 01/16/2025 at approximately 13:48 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: BB11-13/Pad Location ID: 451045 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Sunny, damp w/ patches of snow from prior storm.</p> <p>While there, I observed: Well(s): 6: Producing PR. Battery: Active.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	01/19/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603573	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6881860