

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2025

Submitted Date:

01/14/2025

Document Number:

710500420**FIELD INSPECTION FORM**Loc ID 307865 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
Waggoner, Kyle		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258244	WELL	PR	07/01/2012	CBM	071-07087	GROUSE 13-36	EI
427440	WATER GATHERING SYSTEM/LINE	AC			-	Raton Basin Water Gathering 427440	EI
488964	SPILL OR RELEASE	AC			-	Grouse 13-36 Spill	EI

General Comment:

This is an Environmental Inspection in response to a Produced Water Spill on the Grouse 13-36, API # 05-071-07087, Produced Water Gathering Line ID # 427440, Spill Facility ID 488964, reported on 1/10/2025.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				corrective date
Type: Flow Line	#			
Comment:		Release occurred on 2" valve on Flowline.		
Corrective Action:		Operator shall coordinate with ECMC Engineering Integrity Unit on root cause/corrective action of Spill from flowline and repair/pressure testing of flowline. Test, repair or replace valve per rule 1103.a.		Date: 01/20/2025
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 4.3

Comment: Evergreen Natural Resources, ECMC Operator ID 10705, reported a produced water spill on 1/10/2025 via email notification to the ECMC. A 2-inch valve on the produced water gathering line at the Grouse 13-36 well location, gathering line ID 427440 parted releasing approximately 4.3 bbl. of produced water. Produced water flowed northeast from the Grouse 13-36 well location along a private access road. Produced water entered a dry gully where it flowed northeast to a main ravine identified as waters of the state. Operator filed an initial Form 19 Document # 404054554, reporting the incident to the ECMC on 1/10/2025. ECMC conducted a Field Inspection on 1/10/2025, @ 11:53 a.m. At the time of inspection, there was a fresh blanket of snow covering the location. ECMC was able to follow the spill path northeast along the access road to a culvert where the water entered a gully and flowed north, northeast to a ravine where the produced water entered an area designated as water of the state. At the time of inspection, there was no visible evidence of hydrocarbon impacts along the access road, or gully.

Corrective Action: Operator shall continue spill investigation and cleanup efforts in accordance with Rule 912.b. Operator shall submit a Supplemental Form 19 within 10 days of spill date. In addition, Operator shall adhere to Corrective Actions assigned to Spill Facility ID 488964 in Initial Form 19 Document # 404054554.

Date: 01/20/2025

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404057058	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6875109
710500421	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6875105