

Inspection Photos

Loc: 324795

Operator: WESTERN OPERATING COMPANY

Inspection Date: 1/14/2025

County: Kiowa



Inspection Photos



Photo 1. Facing northeast at the location.



Inspection Photos



Photo 2. Facing north where the tank battery was location. The reclamation has not commenced at this location.



Inspection Photos



Photo 3. Facing northeast toward the wellsite. The well has been plugged and abandoned. The pumpjack and electric utilities must be removed.



Inspection Photos



Photo 4. There is an open excavation at the wellhead from remediation. This area needs to be protected to prevent wildlife or livestock from falling in.



Inspection Photos



Photo 5. It appears this pile is impacted soils from the excavation. This pile is not stored with liner or berm to prevent contamination. Impacted soils need to be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 324795 | Date: 1/14/2025

Inspection Photos



Photo 6. Facing southwest toward the disturbance area of the tank battery. It appears there may be impacted soils that will need to be remediated and reclaimed.



Inspection Photos




Photo 7. 2023 Aerial image of the Foster #1 location. There are impacts from historic spills that will need to be remediated.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 324795 | Date: 1/14/2025