

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Photo # 9520 From entrance to location




Photo # 9521 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Photo # 9522 Location



Photo # 9523 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Photo # 9524 Location



Photo # 9525 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Jan 16, 2025 at 12:09:19 PM
CO

Photo # 9526 Location



Jan 16, 2025 at 12:09:45 PM
CO

Photo # 9527 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Photo # 9528 Location




Photo # 9529 Tank label damaged & some required info is becoming illegible



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Photo # 9530 CIRCLE B LAND 14C-35-692 well bradenhead line connected to blowdown tank



Photo # 9531 CIRCLE B LAND 14C-35-692 well bradenhead line connected to blowdown tank



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Photo # 9532 CIRCLE B LAND 14C-35-692 well bradenhead line connected to blowdown tank



Photo # 9533 Unused hose in secondary containment



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695




Photo # 2573 From inspection 708905205 conducted on 12/06/2024 Blowdown tank label weathered & illegible /does not comply with CECMC rules. Additionally capacity on tank label is also incorrect



Photo # 9534 Blowdown tank label weathered & illegible /does not comply with CECMC rules. Additionally capacity on tank label is also incorrect

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Photo # 2574 From inspection 708905205 conducted on 12/06/2024 Capacity on tank label for blowdown tank is incorrect/does not comply with CECMC rules



Photo # 9535 Capacity on tank label for blowdown tank is incorrect/does not comply with CECMC rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Dec 6, 2024 at 1:04:36 PM
CO

Photo # 2576 From inspection 708905205 conducted on 12/06/2024 Secondary containment insufficient/does not comply with CECMC rules



Jan 16, 2025 at 12:15:11 PM
CO

Photo # 9536 Secondary containment insufficient/does not comply with CECMC rules