

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/16/2025

Submitted Date:

01/21/2025

Document Number:

708905547

**FIELD INSPECTION FORM**

Loc ID 311612	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 32 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> ECMC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269872	WELL	PR	07/02/2012	GW	045-09416	LAST DANCE 12-2	PR

**General Comment:**

CECMC Inspection Report Summary  
 On 01/16/2025 at approximately 12:34 hours, I, Compliance Specialist, Wayne Smelser  
 Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC LAST DANCE 12-2  
 Location # 311612 in Garfield County Colorado.  
 Please refer to inspection 708905240 conducted on 12/06/2024, 1 of 2 previous corrective actions has been completed.  
 Location is within High Priority/Density/Black Bear Habitat areas.  
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Signs/Marker - Methanol tank label missing required information with a CA date of 02/20/2025
2. Equipment - Open ended load line with a CA date of 12/21/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.  
 This is a summary of inspection report.

Dual lease - shared facilities with LAST DANCE 13B-2-792, location # 334763

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	OTHER			
Comment:	Sign at intersection of Dry Hollow road & lease road			
Corrective Action:			Date:	
Type	BATTERY			
Comment:	Battery sign weathered & cracking but still legible at this time			
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:	Methanol tank label from previous inspection has been replaced, however new label is missing some required information			
Corrective Action:	Comply with CECMC labeling rules		Date:	02/20/2025
Type	CONTAINERS			
Comment:	Chemical tank			
Corrective Action:			Date:	
Type	OTHER			
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.			
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	911/970-285-9377			
Corrective Action:			Date:	
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Debris - please refer to photo log			
Corrective Action:			Date:	
Type	UNUSED EQUIPMENT			
Comment:	Unused hose in secondary containment - please refer to photo log			
Corrective Action:			Date:	
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b><u>Fencing/:</u></b>			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tank - Cattle panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pig station - Cattle panels		
Corrective Action:		Date:	

<b><u>Equipment:</u></b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	Last dance QB Energy piggyback		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Open ended hose/load line - additionally this is also a wildlife hazard		
Corrective Action:	Comply with CECMC rules	Date:	12/21/2024
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible		

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gal
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Separate containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	HEATED STEEL AST		,
Comment:	Tank not equipped with telemetry				
Corrective Action:					

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate					
Comment: Centralized containment						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	<50 BBLs	STEEL AST		,	
Comment:						
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity) 500 gal						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate					
Comment: Separate containment						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	200 BBLs	HEATED STEEL AST		,	
Comment: 1 of the 5 tanks is equipped with telemetry						
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate					
Comment: Centralized containment						
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
Flaring:						
Type						
Comment:						

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	269872	Type:	WELL	API Number:	045-09416	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				
		Gravel				Sparse to none in sections
		Culverts				
Compaction						
		Ditches				
Ditches						
				Material Handling And Spill Prevention		Chemical tank containment

Comment: [Some fluid in chemical tank containment, may need maintenance in the near future.](#)

[Limited Stormwater inspection due to snow](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Signs/Marker &amp; Equipment for corrective actions &amp; also refer to Housekeeping for comments.</a>	smelserw	01/21/2025
<a href="#">Dual lease - shared facilities with LAST DANCE 13B-2-792, location # 334763</a>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905548	Inspection 708905547 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6884766">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6884766</a>
708905549	Inspection 708905547 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6884767">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6884767</a>