

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/21/2025

Submitted Date:

01/22/2025

Document Number:

711901810

**FIELD INSPECTION FORM**

Loc ID: 312141 Inspector Name: SCHURE, KYM On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10017  
Name of Operator: CHACO ENERGY COMPANY  
Address: P O BOX 1587  
City: DENVER State: CO Zip: 80201

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Nelson, Matt	303-981-3840	matt@chacoenergy.com	Inspections/Ops. Engineer

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218838	WELL	PR	03/01/2020	OW	075-05599	WRITEBOL 3	PR

**General Comment:**

MIRU - WO  
FORM 42 RECEIVED DOC#404065576

**Inspected Facilities**

Facility ID: 218838 Type: WELL API Number: 075-05599 Status: PR Insp. Status: PR

**Producing Well**

Comment: MIRU - WO

Corrective Action:

Date:

**Workover**

Comment: INSPECT-REPAIR- TESTING TUBING UNEXPECTED WO

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
MIRU	schureky	01/22/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404065970	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6885538">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6885538</a>