

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/22/2025

Submitted Date:

01/22/2025

Document Number:

696307150**FIELD INSPECTION FORM**Loc ID 461773 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10670Name of Operator: BISON IV OPERATING LLCAddress: 518 17TH STREET SUITE 1800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Buck, Paul	303-882-5868	pbuck@bisonog.com	ALL INSPECTIONS
Milne, Rachael	720-370-8580	rmilne@bisonog.com	
Garza, Tarah	970-514-3581	tgarza@bisonog.com	Environmental Compliance Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
461773	Location	AC			-	Fabrizius 27-12, 14, 42, 44	AC

General Comment:[This is a Tank Battery Field Compliance Audit](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					

Corrective Action:						Date:				
<u>Paint</u>										
Condition		Adequate								
Other (Content)										
Other (Capacity)										
Other (Type)										
<u>Berms</u>										
Type		Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:						Shares berm with the Crude Oil Tanks				
Corrective Action:								Date:		
Contents		#	Capacity		Type		Tank ID		SE GPS	
PRODUCED WATER		1	500 BBLs		FIBERGLASS AST				,	
Comment:										
Corrective Action:								Date:		
<u>Paint</u>										
Condition		Adequate								
Other (Content)										
Other (Capacity)										
Other (Type)										
<u>Berms</u>										
Type		Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:						Shares berm with the Crude Oil Tanks				
Corrective Action:								Date:		
Contents		#	Capacity		Type		Tank ID		SE GPS	
CRUDE OIL		1	300 BBLs		STEEL AST				,	
Comment:										
Corrective Action:								Date:		
<u>Paint</u>										
Condition		Adequate								
Other (Content)										
Other (Capacity)										
Other (Type)										
<u>Berms</u>										
Type		Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:						Shares berm with the other Crude Oil Tanks				
Corrective Action:								Date:		
Contents		#	Capacity		Type		Tank ID		SE GPS	

CRUDE OIL	2	500 BBLs	STEEL AST		40.892560,-104.892560	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:		Date:				
Venting:						
Yes/No						
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 461773

Type: Location

API Number: -

Status: AC

Insp. Status: AC

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: SI - Location Shut-In at the time of this Field Compliance Audit

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Routine Field Compliance Audit	petrie	01/22/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696307151	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6885968