

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/23/2025

Submitted Date:

01/23/2025

Document Number:

713301568**FIELD INSPECTION FORM**Loc ID 317801 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone        | Email         | Comment                         |
|--------------|--------------|---------------|---------------------------------|
| , KPK        | 303-825-4822 | cogcc@kpk.com | <a href="#">all inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name           | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 239995      | WELL | PR     | 02/01/2024  | GW         | 123-07783 | ROCKY MOUNTAIN FUEL C 5 | PR          |

**General Comment:**[well site inspection](#)

**Location**Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | good     |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  | Date: _____ |
| Corrective Action: |  |             |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |                                   |       |  |
|--------------------|-----------------------------------|-------|--|
| Type               | PUMP JACK                         |       |  |
| Comment:           | safety guard                      |       |  |
| Corrective Action: |                                   | Date: |  |
| Type               | OTHER                             |       |  |
| Comment:           | electric disconnect, metal panels |       |  |
| Corrective Action: |                                   | Date: |  |

**Equipment:**

|                           |                            |       |                 |
|---------------------------|----------------------------|-------|-----------------|
|                           |                            |       | corrective date |
| Type: Pump Jack           | # 1                        |       |                 |
| Comment:                  |                            |       |                 |
| Corrective Action:        |                            | Date: |                 |
| Type: Ancillary equipment | # 4                        |       |                 |
| Comment:                  | automation/electric panels |       |                 |
| Corrective Action:        |                            | Date: |                 |
| Type: Bradenhead          | # 1                        |       |                 |
| Comment:                  | piped to surface           |       |                 |
| Corrective Action:        |                            | Date: |                 |
| Type: Prime Mover         | # 1                        |       |                 |
| Comment:                  | electric                   |       |                 |
| Corrective Action:        |                            | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

Inspected Facilities

Facility ID: 239995 Type: WELL API Number: 123-07783 Status: PR Insp. Status: PR

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE  
Comment: Valves appeared to be closed at time of inspection  
Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 03/19/2024 Annual Brhd Completed? Yes  
Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:  
End Surf Csg Pressure: 0  
Comment:  
Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment  | User    | Date       |
|--|---------|------------|
| Audit of scout card and related documents<br>Routine inspection<br><br>This inspection does not nullify any orders or NOAV from the ECMC | kesterm | 01/23/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 713301569    | site pic    | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6887734">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6887734</a> |