

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/23/2025

Submitted Date:

01/23/2025

Document Number:

715800566

**FIELD INSPECTION FORM**

Loc ID 318491 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Norton, Mathew		mnorton@kpk.com	
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241403	WELL	PR	06/01/2023	GW	123-09192	JILLSON 5	SI

**General Comment:**

[This is a WO/P&A audit & field inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

**Good Housekeeping:**

Type			
Comment:	Location is snow covered		
Corrective Action:			Date:

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:			
Corrective Action:			Date:

**Equipment:**

			corrective date
Type: Prime Mover	# 0		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 0		
Comment:			
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 241403 Type: WELL API Number: 123-09192 Status: PR Insp. Status: SI

**Cement**

Cement Contractor

Contractor Name: Duco Inc. Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 490' - 0' Cement Volume (sx): 167

Good Return During Job: YES Cement Type: G

Comment: Duco Cement crew nipple up to WH & pressure test lines to 500 psi. Begin mixing, weighting up & pumping a surface plug with 150 sxs of type G cement to 15.8 lbs. with good cement returns to the circulation tank.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI with active P&A operations, Form 42 (MIRU)-00 Doc # 404048990 & 42(PA)-00 Doc # 404049000.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/05/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0

Comment: Plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Workover**

Comment: At the time of this inspection the WO rig crew was prepping the WH to pump cement.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
This Audit/Inspection is due to a form 42 MIRU doc # 404048990 & a form 42 PA doc # 404049000. Weather: Clear Temperature: 28* Location: Snow covered.	revasr	01/23/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800567	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6887826">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6887826</a>