

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/21/2025

Submitted Date:

01/23/2025

Document Number:

708303342

**FIELD INSPECTION FORM**

Loc ID 335431 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                              | Comment |
|--------------|-------|------------------------------------|---------|
| , TEP        |       | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 266384      | WELL | PR     | 12/09/2003  | GW         | 045-09146 | PA 312-33     | PR          |
| 269556      | WELL | PR     | 12/08/2003  | GW         | 045-09380 | PA 412-33     | PR          |

**General Comment:**

[CECMC Inspection Report Summary](#)

On 1/21/2025 at approximately 11:55, Compliance Inspector Matthew Morris conducted an on-site audit at TEP ROCKY MOUNTAIN LLC, PA-66S95W/33SWNW at Location ID #335431 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |                   |       |  |
|--------------------|-------------------|-------|--|
| Comment:           | 911/(970)285-9377 | Date: |  |
| Corrective Action: |                   |       |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |            |       |  |
|--------------------|------------|-------|--|
| Type               | WELLHEAD   |       |  |
| Comment:           | Hog panels |       |  |
| Corrective Action: |            | Date: |  |

**Equipment:**

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| Type: Bradenhead   | # 2 |       | corrective date |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |
| Type: Plunger Lift | # 2 |       |                 |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 266384 Type: WELL API Number: 045-09146 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 269556 Type: WELL API Number: 045-09380 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       |                 |                         |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |
|                  |                 | Check Dams              |                       |               |                          |         |
|                  |                 | Compaction              |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
|                  |                 | Culverts                |                       |               |                          |         |
|                  |                 | Tracking Pad            |                       |               |                          |         |
|                  |                 | Rip Rap                 |                       |               |                          |         |
|                  |                 | Sediment Traps          |                       |               |                          |         |

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment  | User    | Date       |
|--|---------|------------|
| <span style="color: blue;">Wellheads only. Separators &amp; production tank located on the MOBIL PA 12-33 Pad, Location ID: #323950</span> | morrism | 01/23/2025 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 708303343    | Photo Log   | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6888139">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6888139</a> |