

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC WHF/D17 998

Location ID: 429734

Date: 01/23/2025



Jan 23, 2025 at 2:01:29 PM
+39.277665,-108.359934 ±2.70m
De Beque



Jan 23, 2025 at 2:44:46 PM
+39.277461,-108.359678 ±3.57m
De Beque

Photo # 3307 Entrance to location

Photo # 3340 Location

Inspection/Audit Photos
Location: LARAMIE ENERGY LLC WHF/D17 998
Location ID: 429734
Date: 01/23/2025



Jan 23, 2025 at 2:07:24 PM
+39.277566,-108.359159 ±5.92m
De Beque



Jan 23, 2025 at 2:08:24 PM
+39.277599,-108.358889 ±5.51m
De Beque

Photo # 3309 Location

Photo # 3311 Location

Inspection/Audit Photos
Location: LARAMIE ENERGY LLC WHF/D17 998
Location ID: 429734
Date: 01/23/2025



Photo # 3325 Location



Photo # 3331 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC WHF/D17 998

Location ID: 429734

Date: 01/23/2025



Photo # 3339 Location



Photo # 3355 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC WHF/D17 998

Location ID: 429734

Date: 01/23/2025



Photo # 3360 NW corner of location



Photo # 3361 SW corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC WHF/D17 998

Location ID: 429734

Date: 01/23/2025



Photo # 3362 SE corner of location



Photo # 3363 NE corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC WHF/D17 998

Location ID: 429734

Date: 01/23/2025



Photo # 3324 Failure to maintain chemical BMP/chemical containment approximately 3/4th full of fluid/not sufficient to contain possible spill

Photo # 3366 Debris

Inspection/Audit Photos
Location: LARAMIE ENERGY LLC WHF/D17 998
Location ID: 429734
Date: 01/23/2025



Photo # 3367 Debris



Photo # 3368 Debris

Inspection/Audit Photos
Location: LARAMIE ENERGY LLC WHF/D17 998
Location ID: 429734
Date: 01/23/2025



Photo # 3370 Debris

Photo # 3374 Debris

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC WHF/D17 998

Location ID: 429734

Date: 01/23/2025




Photo # 3379 Label is showing signs of disrepair