

# Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIT BOTTOM RANCH/SG 23-22 PAD

Location ID: 435460

Date: 01/21/2025



Jan 21, 2025 at 1:38:00 PM  
+39.421003,-108.099450 ±4.57m  
De Beque



Jan 21, 2025 at 2:47:28 PM  
+39.421533,-108.100085 ±7.52m  
De Beque

TEP Rocky Mountain LLC

970-285-9377

SG 23-22 PAD

COC 36219 COC 58673

SG 13-22 SG 12-22

SG 313-22 SG 22-22

SG 413-22 SG 312-22

SG 513-22 SG 322-22

SG 412-22

SG 422-22

SG 512-22

SG 521-22

SG 522-22

NESW SEC. 22/T7S/R96W

GARFIELD COUNTY, CO

EMS 911

ACCESS FROM: HWY 6 & 24

Photo # 3019 Entrance to location

Photo # 3085 Location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIT BOTTOM RANCH/SG 23-22 PAD

Location ID: 435460

Date: 01/21/2025



Photo # 3020 Location



Photo # 3021 Location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIT BOTTOM RANCH/SG 23-22 PAD

Location ID: 435460

Date: 01/21/2025



Photo # 3036 Location



Photo # 3058 Location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIT BOTTOM RANCH/SG 23-22 PAD

Location ID: 435460

Date: 01/21/2025



Photo # 3059 Location



Photo # 3062 Location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIT BOTTOM RANCH/SG 23-22 PAD

Location ID: 435460

Date: 01/21/2025



Photo # 3084 Location



Photo # 3091 NW corner of location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIT BOTTOM RANCH/SG 23-22 PAD

Location ID: 435460

Date: 01/21/2025



Photo # 3092 SW corner of location



Photo # 3093 SE corner of location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIT BOTTOM RANCH/SG 23-22 PAD

Location ID: 435460

Date: 01/21/2025



Photo # 3094 NE corner of location



Photo # 3039 Chemical tanks lack required labeling/do not comply with CECMC rules

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIT BOTTOM RANCH/SG 23-22 PAD

Location ID: 435460

Date: 01/21/2025



**Photo # 3074 PRV vent lines do not comply with CECMC pressure safety device rules**



**Photo # 3076 PRV vent lines do not comply with CECMC pressure safety device rules**

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIT BOTTOM RANCH/SG 23-22 PAD

Location ID: 435460

Date: 01/21/2025



Photo # 3077 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3023 Paint staining the ground around equipment & flowlines in multiple areas on location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIT BOTTOM RANCH/SG 23-22 PAD

Location ID: 435460

Date: 01/21/2025



Photo # 3027 Paint staining the ground around equipment & flowlines in multiple areas on location



Photo # 3035 Paint staining the ground around equipment & flowlines in multiple areas on location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC STRAIT BOTTOM RANCH/SG 23-22 PAD

Location ID: 435460

Date: 01/21/2025



**Photo # 3065 Paint staining the ground around equipment & flowlines in multiple areas on location**



**Photo # 3066 Paint staining the ground around equipment & flowlines in multiple areas on location**