


Inspection Photos
Location Name: Miller 22-08 1N44W
API Number: 125-11680



1. Lease sign at well location.



2. View of wellhead. Note dried vegetation inside fencing.

Inspection Photos
Location Name: Miller 22-08 1N44W
API Number: 125-11680




3. Black poly line outside well fencing.



4. Well location overview.

Inspection Photos
Location Name: Miller 22-08 1N44W
API Number: 125-11680



5. Lease sign at remote tank/gathering location.



6. Gas meter inside meter shed.

Inspection Photos
Location Name: Miller 22-08 1N44W
API Number: 125-11680



7. Produced water tank at remote battery. Note labels/stickers are peeling and require replacement.



8. View of metal containment wall around tank that has rusted through at grade level.