

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/22/2025

Submitted Date:

01/24/2025

Document Number:

715201577**FIELD INSPECTION FORM**Loc ID 321944 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 88380Name of Operator: TINDALL OPERATING COMPANYAddress: P.O. BOX 4507City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Tucker, Lee	303-850-7272	rleetuck@aol.com	
Witzel, Carrie		clwitzel@hotmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208639	WELL	SI	06/01/2024	GW	017-07574	UPR 1-25	PA

General Comment:

SE Compliance Specialist Brian Welsh conducted a Routine field inspection of the location

Location

Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment still present at meter run		
Corrective Action:	Remove equipment to begin final reclamation process	Date:	01/31/2025
Type: Gas Meter Run	# 1		
Comment:	Meter run equipment is still on location		
Corrective Action:	Remove equipment to begin final reclamation process	Date:	01/31/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	300 BBLS	FIBERGLASS AST		38.898910,-102.053230
Comment:	Tank has been removed from location				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No		
--------	--	--

Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 208639 Type: WELL API Number: 017-07574 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well has been plugged. The operator has 30 days after well plugging to remove equipment and begin final reclamation process. Wellhead location has been ripped and tank battery location has been ripped. Finish removing remaining equipment and continue with reclamation process	welshb	01/24/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201603	Meter run equipment	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892044
715201604	Wellhead location	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892045