


Inspection Photos
Location Name: Miller 32-08 1N44W
API Number: 125-11681



1. Lease sign at well location.



2. View of wellhead. Note dried vegetation inside fencing.

Inspection Photos
Location Name: Miller 32-08 1N44W
API Number: 125-11681



3. Well location overview. Note black poly visible against fencing.



4. Lease sign at remote gathering location.

Inspection Photos
Location Name: Miller 32-08 1N44W
API Number: 125-11681



5. Gas meter inside meter shed.



6. Produced water tank. Note labels/stickers peeling.

Inspection Photos
Location Name: Miller 32-08 1N44W
API Number: 125-11681



7. Metal containment is rusted through at grade. Note visible daylight along base of metal wall.



8. Remote tank/gathering location overview.