

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/21/2025

Submitted Date:

01/21/2025

Document Number:

708303336**FIELD INSPECTION FORM**Loc ID 334724 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210762	WELL	PR	11/01/1984	GW	045-06520	HOOAGLUND W-25-2	PR
210951	WELL	PR	11/10/1990	GW	045-06709	HOAGLUND GV 65-2	PR
283974	WELL	PR	03/23/2006	GW	045-12049	HOAGLUND PA 411-2	PR
283975	WELL	PR	03/23/2006	GW	045-12050	HOAGLUND PA 511-2	PR
283976	WELL	PR	03/23/2006	GW	045-12051	HOAGLUND PA 311-2	PR
283977	WELL	PR	03/23/2006	GW	045-12052	HOAGLUND PA 12-2	PR
283978	WELL	PR	03/23/2006	GW	045-12053	HOAGLUND PA 312-2	PR
283979	WELL	PR	03/23/2006	GW	045-12054	HOAGLUND PA 412-2	PR

**General Comment:****CECMC Inspection Report Summary**

On 1/21/2025 at approximately 11:15, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW at Location ID #334724 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Wildlife entry hazard at gas meter housing

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Stored supplies on line heater. Remove stored supplies.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 8		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Line heater		
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:	Wildlife entry hazard on gas meter housing for GV 65-2.		
Corrective Action:	Secure equipment to prevent wildlife entry.		Date: 01/27/2025
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						
Date:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						

Corrective Action:					Date:	
--------------------	--	--	--	--	-------	--

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

Flaring:

Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities						
Facility ID:	210762	Type:	WELL	API Number: 045-06520	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	210951	Type:	WELL	API Number: 045-06709	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	283974	Type:	WELL	API Number: 045-12049	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	283975	Type:	WELL	API Number: 045-12050	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	283976	Type:	WELL	API Number: 045-12051	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	283977	Type:	WELL	API Number: 045-12052	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	283978	Type:	WELL	API Number: 045-12053	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	283979	Type:	WELL	API Number: 045-12054	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:						
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						

Producing Well			
Comment:			
Corrective Action:			Date: <div></div>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Gravel						
Berms						
		Culverts				
Compaction						
		Gravel				
		Ditches				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.  
Lease road repair of stormwater damage is complete.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404065295	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6884816">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6884816</a>
708303337	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6884811">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6884811</a>