

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2025

Submitted Date:

01/28/2025

Document Number:

717100051**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Rollins, Grace 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections
Brown, Kari		kari.oakman@state.co.us	
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Graber, Nikki		nikki.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488882	SPILL OR RELEASE	CL	12/19/2024		-	HSR-Miller Fed 5-7A Wellhead	EI

General Comment:**ECMC Environmental Field Inspection Report Summary**

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 488882

Spill Name: HSR-Miller Fed 5-7A Wellhead

Remediation Project #: 35592

Wellhead API #: 05-123-19985

Reported Date of Discovery: 12/17/2024

Date of Inspection: 01/15/2025

Spill is located within or adjacent to:

- Bald Eagle Roost Site
- Wetlands
- 100-year floodplain
- Livestock rangeland

Current site status:

- Excavation has been backfilled.
- Trash observed along the length of the lease road.
- Wildlife tracks observed.

See attached corrective actions. A Supplemental Form 27 is required.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	TRASH			
Comment:	Trash observed along the length of the lease road.			
Corrective Action:	Comply with Rule 606.			Date: 02/04/2025
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: _____
Flaring:				
Type				
Comment:				
Corrective Action:				Date: _____

Inspected Facilities									
Facility ID:	488882	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation Project No. 35592 was created for the plugging and abandonment of the HSR-Miller Fed 5-7A wellhead and the removal of the associated flowline. The excavation at the spill location has been backfilled. No environmental impacts were visible. Quarterly reporting was required under Remediation Project No. 35592; the last Form 27 for this project was submitted 05/30/2024 (Document No. 403791790).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project No. 35592.

Date: 02/13/2025

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100054	ECMC Photo Log - HSR-Miller Fed 5-7A Wellhead	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892527