

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2025

Submitted Date:

01/28/2025

Document Number:

717100056

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Rollins, Grace 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Brown, Kari		kari.oakman@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
489008	SPILL OR RELEASE	CL			-	Weld CTY2/Klitz9-26A Facility	EI

General Comment:**ECMC Environmental Field Inspection Report Summary**

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 489008

Spill Name: Weld CTY2/Klitz9-26A Facility

Remediation Project #: 37457

Fac ID: 488191

Reported Date of Discovery: 01/06/2025

Date of Inspection: 01/10/2025

- Two excavations remain open with snow accumulation.
- Metal fencing surrounds both excavations.
- Gray staining observed within northern excavation.
- Flowline risers were present within the southern excavation.
- Unmarked soil was stockpiled on location with inadequate stormwater BMPs.

See attached corrective actions. A Supplemental Form 27 is required.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:		<div>Signage with emergency contact number is present.</div>		
Corrective Action:		<div></div>		Date: <div></div>
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:		<div></div>		
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	<div>Metal fencing surrounds the excavations.</div>			
Corrective Action:	<div></div>			Date: <div></div>
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: <div></div>
Flaring:				
Type				
Comment:				
Corrective Action:				Date: <div></div>

Inspected Facilities									
Facility ID:	489008	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation Project No. 37457 was created for closure of the Weld CTY2/Klitz9-26A Facility. Two excavations remain open with snow accumulation. Metal fencing surrounds both excavations. Gray staining observed within northern excavation. Flowline risers were are present within the southern excavation. Quarterly reporting was required under Remediation Project No. 37457; the last From 27 for this project was submitted 10/22/2024 (Document No. 403902648).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project No. 37457.

Date: 02/11/2025

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Spill/Remediation:

Comment: Unmarked soil was stockpiled on location with inadequate stormwater BMPs.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 02/11/2025

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100057	ECMC Photo Log - Weld CTY2/Klitz9-26A Facility	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892605