

ECMC Environmental Field Inspection Report Summary

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 488931

Remediation Project #: 37053

Spill Name: Windell 4-18A Wellhead

Wellhead API #: 05-123-20649

Reported Date of Discovery: 12/26/2024

Date of Inspection: 01/15/2025

Spill is located within or adjacent to:

-Fort Lupton Municipality

-South Platte River

-Wetlands

-Bald Eagle Active Nest Site Half Mile / Bald Eagle Active Nest Site Qtr Mile

-Bald Eagle Roost Site

-Mule Deer Migration Corridor

-Mule Deer Winter Concentration Area / Mule Deer Severe Winter Range

-Aquatic Native Species Conservation Waters

-100-year floodplain

Current site status:

-Excavation has been backfilled.

-Metal fencing surrounds former wellhead/spill location.

-Ruts and small piles of soil observed near the former wellhead.

See attached corrective actions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: Ruts and small piles of soil observed near the former wellhead.

Corrective Action: Comply with Rule 1002.f.(2)C

Date: 02/12/2025

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: Metal fencing surrounds former wellhead/spill location. Excavation has been backfilled.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 488931 Type: SPILL OR API Number: - Status: CL Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Remediation Project No. 37053 was created for the plugging and abandonment of the Windell 4-18A Wellhead wellhead and the removal of the associated flowline. The excavation at the location of the former wellhead has been backfilled. Metal fencing surrounds the former wellhead. No environmental impacts were visible. Quarterly reporting is required under Remediation Project No. 37053.

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100047	ECMC Photo Log - Windell 4-18A Wellhead	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892653