

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/21/2025

Submitted Date:

01/28/2025

Document Number:

717100062**FIELD INSPECTION FORM**Loc ID 464146 Inspector Name: Rollins, Grace On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Brown, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488001	TANK BATTERY	AC	10/01/2024		-	Clark 7-13 Stroh 2 Facility	EI

General Comment:**ECMC Environmental Field Inspection Report Summary**

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Facility ID: 488001

Facility Name: Clark 7-13 Stroh 2 Facility

Remediation Project #: 37425

Date of Inspection: 01/15/2025

Spill is located adjacent to:

- Occupied buildings
- Livestock
- Wetlands
- Weld County Road 46

Current site status:

- Two excavations remain open with snow accumulation.
- No environmental impacts were visible in-situ in exposed areas of the excavations.
- Orange construction fencing is present at open excavations but is beginning to fall in places.
- Orange construction fencing is inadequate for the location as it is the only physical barrier between Weld County Road 46 and the excavations.
- Two unmarked soil stockpiles are on location.

See attached corrective actions. A Supplemental Form 27 is required.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Orange construction fencing is present at open excavations but is beginning to fall in places. Orange construction fencing is inadequate for the location as it is the only physical barrier between Weld Country Road 46 and the excavations.		
Corrective Action:	Secure access to excavation in accordance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v.		Date: 02/11/2025

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	488001	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
	Piles	Adequate		
Comment	Two unmarked soil stockpiles are on location; BMPS are adequate.			
Corrective Action				Date:

Spill/Remediation:

Comment: Remediation Project No. 37425 was created for decommissioning of the Clark 7-13 Stroh 2 Facility. Two excavations remain open with snow accumulation. Quarterly reporting was required under Remediation Project No. 37425; the last Form 27 for this project was submitted 10/04/2024 (Document No. 403931445).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project No. 37425. Date: 02/11/2025

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100063	ECMC Photo Log - Clark 7-13 Stroh 2 Facility	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892656