

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/15/2025

Submitted Date:

01/28/2025

Document Number:

717100064

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 Rollins, Grace _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
 Address: P O BOX 173779
 City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Brown, Kari		kari.oakman@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488937	SPILL OR RELEASE	CL	01/03/2025		-	Jones Guy H Gas UN 2 Wellhead	EI

General Comment:

[ECMC Environmental Field Inspection Report Summary](#)
 Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 488937
 Spill Name: Jones Guy H Gas UN 2 Wellhead
 Remediation Project #: 36864
 Wellhead API #: 05-123-15441
 Reported Date of Discovery: 01/02/2025
 Date of Inspection: 01/15/2025

Spill is located within or adjacent to:
 -Bald Eagle Active Nest Site Qtr Mile HPH
 -Bald Eagle Active Nest Site Half Mile HPH
 -Wetlands

Current site status:
 -Excavation has been backfilled.
 -Sample collection tubing observed at the former wellhead/spill location.
 -No environmental impacts were visible.

See attached corrective actions. A Supplemental Form 27 is required.

Inspected Facilities

Facility ID: 488937 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Remediation Project No. 36864 was created for the plugging and abandonment of the Jones Guy H Gas UN 2 wellhead and the removal of the associated flowline. The excavation has been backfilled. Sample collection tubing observed at the former wellhead/spill location. No environmental impacts were visible. Quarterly reporting was required under Remediation Project No. 36864; the last Form 27 for this project was submitted 08/21/2024 (Document No. 403895850).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project No. 36864.

Date: 02/11/2025

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100065	ECMC Photo Log - Jones Guy H Gas UN 2 Wellhead	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892657