

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2025

Submitted Date:

01/28/2025

Document Number:

717100070**FIELD INSPECTION FORM**Loc ID 318417 Inspector Name: Rollins, Grace On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Graber, Nikki		nikki.graber@state.co.us	
Watzman, Ross		rwatzman@kpk.com	<a href="#">All Inspections</a>
Brown, Kari		kari.oakman@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241258	WELL	PR	12/01/2019	OW	123-09046	SAM FUNAKOSHI A 1	PR
481032	TANK BATTERY	AC	11/03/2021		-	Sam Funakoshi A 1 battery	AC

**General Comment:**

ECMC Environmental Field Inspection Report Summary

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location Name: Sam A. #1 & #2 Tank Battery

Facility ID: 481032

Wellhead Name: Sam Funakoshi A #1 Wellhead

Wellhead API #: 05-123-09046

Date of Inspection: 01/15/2025

Location is within or adjacent to:

-Bald Eagle Active Nest Site Qtr Mile HPH

-Bald Eagle Active Nest Site Half Mile HPH

Current site status:

-Petroleum hydrocarbon staining and a strong odor were observed adjacent to the production tank.

-Residual petroleum hydrocarbon fluids are visible in discarded equipment next to the apparent spill.

-Wildlife scat was observed on petroleum hydrocarbon saturated soil.

-At a second location, petroleum hydrocarbon staining and odor observed were on and beneath the valve of a pipe manifold.

-A riser on the south side of the production tank was missing OOSLAT.

-A surface crack was observed on the crude oil AST and produced water vessel shared berm.

-Weeds were observed on the ancillary equipment berm.

-A wildlife burrow was observed on the separator berm.

-Green staining was observed around ancillary equipment in the location stagnant water was visible in the photo log of previous Field Inspection Report Document No. 715800200).

-Wildlife tracks were observed on the location.

-Signage with emergency contact number was visible at the tank battery and wellhead.

-NFPA placards were visible at the crude oil AST and produced water vessel.

See attached corrective actions.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	NFPA placards were visible at the crude oil AST and produced water vessel.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Signage with emergency contact number was visible at the tank battery and wellhead.		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds were observed on the ancillary equipment berm.		
Corrective Action:	Comply with Rule 606.	Date:	02/04/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Other	#		corrective date
Comment:	A riser on the south side of the production tank was missing OOSLAT.		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.		Date: 01/30/2025

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	A surface crack was observed on the crude oil AST and produced water vessel shared berm. A wildlife burrow was observed on the separator berm.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 02/26/2025

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Location Construction**

Location ID: 481032 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ Date: \_\_\_\_\_

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

Inspected Facilities									
Facility ID:	241258	Type:	WELL	API Number:	123-09046	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	481032	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	AC
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: Petroleum hydrocarbon staining and a strong odor were observed adjacent to the production tank. Residual petroleum hydrocarbon fluids are visible in discarded equipment next to the apparent spill. Wildlife scat was observed on petroleum hydrocarbon saturated soil. At a second location, petroleum hydrocarbon staining and odor observed were on and beneath the valve of a pipe manifold.

Corrective Action: Properly dispose of oily waste in accordance with 905.e and, if applicable, report in accordance with 912. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 02/12/2025

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100077	ECMC Photo Log - Funakoshi, Sam A. #1 & #2 Tank Battery	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892753">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892753</a>
717100078	ECMC Photo Log - Sam Funakoshi A #1 Wellhead	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892754">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892754</a>