

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2025

Submitted Date:

01/28/2025

Document Number:

713301601

**FIELD INSPECTION FORM**

Loc ID 318502 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241423	WELL	SI	04/01/2023	GW	123-09212	UPRR 42 PAN AM AN 1	SI

**General Comment:**

[well site inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	rusty/faded		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	

**Equipment:**

Type	Area	Volume			corrective date
Type: Pump Jack		# 1			
Comment:					
Corrective Action:			Date:		
Type: Bradenhead		# 1			
Comment:	piped to surface				
Corrective Action:			Date:		
Type: Ancillary equipment		# 3			
Comment:	electric/automation panels				
Corrective Action:			Date:		
Type: Prime Mover		# 1			
Comment:	electric				
Corrective Action:			Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 241423 Type: WELL API Number: 123-09212 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Valves appeared to be closed at time of inspection

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 8 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<u>Audit of scout card and related documents</u> <u>Routine inspection</u>	kesterm	01/28/2025
<u>This inspection does not nullify any orders or NOAV from the ECMC</u>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301602	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6893811">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6893811</a>