

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/03/2025

Submitted Date:

01/29/2025

Document Number:

709100479

FIELD INSPECTION FORM

Loc ID 316916 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10690
Name of Operator: IMPETRO RESOURCES LLC
Address: 558 CASTLE PINES PKWY UNIT B-4
City: CASTLE PINES State: CO Zip: 80108

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|-------------------------------|---------------------------------|
| Collin Metz | | collin.metz@state.co.us | |
| Kyle Waggoner | | kyle.waggoner@state.co.us | |
| Bongers, Brent | 361-935-5633 | bbongers@impetroresources.com | All Inspections |
| Abdul Elnajdi | | abdul.elnajdi@state.co.us | |
| Krystal Heibel | | krystal.heibel@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 233182 | WELL | PR | 06/01/2022 | OW | 121-05206 | SCOTT 2 | EI |

General Comment:

On January 3, 2025, ECMC Staff Krystal Heibel, Abdul Elnajdi, and Collin Metz conducted an on-site inspection. This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: Unused equipment on location. Comply with Rule 606.

Corrective Action:

Date:

Overall Good:

Spills:

Type

Area

Volume

Comment: Hydrocarbon stained soil observed around wellhead, on concrete slab, and near pumping unit.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 01/29/2025

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type:

#

Comment: Proper wildlife protection devices on secondary containment for polytank observed.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 233182 Type: WELL API Number: 121-05206 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 709100480 | Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6894435 |