

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2025

Submitted Date:

01/29/2025

Document Number:

713601819

**FIELD INSPECTION FORM**

Loc ID 476137 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96730  
Name of Operator: WILLIFORD ENERGY COMPANY  
Address: 6060 AMERICAN PLAZA SUITE 760  
City: TULSA State: OK Zip: 74135

**Findings:**

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Sanchez, Chris		chris.sanchez@state.co.us	
Storts, Doug		pds@willifordenergy.com	
GROWNS LARRY		lgrowsn@willifordenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476137	LOCATION	AC			-	RHOADES UNIT TUBING FLOWLINE 3213S48W	RI

**General Comment:**

This is a follow up inspection at the RHOADES UNIT Tank Battery Location #476137. See attached photos and additional details within this report.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS			
Comment:	The tanks labels are missing and faded. No NFPA label on some of the tanks.			
Corrective Action:	Install sign to comply with Rule 605.h.		Date:	09/21/2024

**Emergency Contact Number:**

Comment:			
Corrective Action:			Date: _____

**Good Housekeeping:**

Type	UNUSED EQUIPMENT			
Comment:	There have been three unused tanks removed since the previous inspection.			
Corrective Action:			Date:	

Overall Good:

**Spills:**

Type	Area	Volume		
Crude Oil	Tank			
Comment:	There was oil stained soils around the tanks and shed that will need to be cleaned up. There is also oil stains along the flowline going to the heater treater. A form 19 has been submitted since the previous inspection. The form 19 document #403977660 requires multiple Conditions of Approval which have not been completed.			
Corrective Action:	Immediately Comply with form 19 document #403977660 COA's.			Date:

In Containment: Yes \_\_\_\_\_

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No				
Comment:				
Corrective Action:			Date:	

**Flaring:**

Type				
Comment:				
Corrective Action:			Date:	

**Environmental**

**Spills/Releases:**

Type of Spill: CONDENSATE

Estimated Spill Volume: \_\_\_\_\_

Comment: There has been a new spill that occurred at the Rhoades Unit Tank Battery. There was a leak at the heater treater that spilled hydrocarbon mist along the west side berm. It appears the leak flowed to the southeast corner of the location. There was also a condensate leak that occurred from the fiberglass tank and flowline shed. It appears this leak overtopped the berm at the southeast coner.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Report spill or release of E&P waste or produced fluids Remove free fluids and contact ECMC EPS staff per Rule 912.b.

Date: 01/30/2025

Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601820	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6895100">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6895100</a>