

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2025

Submitted Date:

01/29/2025

Document Number:

717100091**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Rollins, Grace 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name        | Phone | Email                          | Comment                           |
|---------------------|-------|--------------------------------|-----------------------------------|
| Mickelson, Erik     |       | Erik_Mickelson@oxy.com         | <a href="#">Oxy Environmental</a> |
| Graber, Nikki       |       | nikki.graber@state.co.us       |                                   |
| ,                   |       | ECMCInspections@Oxy.com        | <a href="#">All Inspections</a>   |
| Ahmadian, Alexander |       | alexander.ahmadian@state.co.us |                                   |
| Metz, Collin        |       | collin.metz@state.co.us        |                                   |

**Inspected Facilities:**

| Facility ID | Type             | Status | Status Date | Well Class | API Num | Facility Name         | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|-----------------------|-------------|
| 487769      | SPILL OR RELEASE | CL     |             |            | -       | Highum, Norden, Clark | EI          |

**General Comment:**

ECMC Environmental Field Inspection Report Summary

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 487769

Spill Name: Highum, Norden, Clark

Remediation Project #: 36732

Facility ID: 335610

Reported Date of Discovery: 09/05/2024

Date of Inspection: 01/24/2025

Spill is located in close proximity to two additional spills:

Spill ID: 479618

Spill Name: Keifer George W U B #1A

Spill Operator: KP KAUFFMAN COMPANY INC (KPK)

and

Spill ID: 489119

Spill Name: Keifer George B#1 Line Strike

Spill Operator: KP KAUFFMAN COMPANY INC (KPK)

Current site status (Spill ID 489119):

-An excavation remains open on location with metal fencing installed.

-The western portion of the excavation was deepened in response to recent Spill ID 489119, which will be addressed in a separate inspection.

-The eastern portion of the excavation was opened in response to Historical Spill ID 487769/Remediation Project No. 36732.

-Gray staining is visible on the excavation sidewalls in-situ.

-Great Western Midstream and United Power underground utility flags and markings were visible on location.

-Two soil stockpiles were on location, one of which was marked "Topsoil Storage" and the other was unmarked. BMPs are adequate.

See attached corrective actions. A Supplemental Form 27 is required.

|  |  |        |  |       |             |
|--|--|--------|--|-------|-------------|
| Location   |  |        |  |       |             |
| Overall Good: <input type="checkbox"/>                 |  |        |  |       |             |
| Emergency Contact Number:                              |  |        |  |       |             |
| Comment:   |  |        |  |       | Date: _____ |
| Corrective Action:                                     |  |        |  |       |             |
| Overall Good: <input type="checkbox"/>                 |  |        |  |       |             |
| <b>Spills:</b>   |  |        |  |       |             |
| Type   | Area   | Volume |  |       |             |
| In Containment: No                                     |  |        |  |       |             |
| Comment:   |  |        |  |       |             |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |  |       |             |
| <b>Fencing/:</b>                                       |  |        |  |       |             |
| Type   | OTHER  |        |  |       |             |
| Comment:   | An excavation remains open on location with metal fencing installed. |        |  |       |             |
| Corrective Action:                                     |  |        |  | Date: |             |
| <b>Venting:</b>  |  |        |  |       |             |
| Yes/No   |  |        |  |       |             |
| Comment:   |  |        |  |       |             |
| Corrective Action:                                     |  |        |  | Date: |             |
| <b>Flaring:</b>  |  |        |  |       |             |
| Type   |  |        |  |       |             |
| Comment:   |  |        |  |       |             |
| Corrective Action:                                     |  |        |  | Date: |             |

| Inspected Facilities   |        |       |          |             |   |         |    |               |    |
|--|--------|-------|----------|-------------|---|---------|----|---------------|----|
| Facility ID:   | 487769 | Type: | SPILL OR | API Number: | - | Status: | CL | Insp. Status: | EI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |   |         |    |               |    |
|  |        |       |          |             |   |         |    |               |    |

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: Remediation Project No. 36732 was created for decommissioning of the Highum, Norden, Clark facility. An excavation remains open at the location. The eastern portion of the excavation was opened in response to Historical Spill ID 487769/Remediation Project No. 36732. The western portion of the excavation was deepened in response to recent Spill ID 489119, which will be addressed in a separate inspection. Gray staining is visible on the excavation sidewalls in-situ. Quarterly reporting was required under Remediation Project No. 36732; the last Form 27 for this project was submitted 10/22/2024 (Document No. 403930193).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project No. 36732.

Date: 02/12/2025

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Waste Management:**

Type \_\_\_\_\_ Management \_\_\_\_\_ Condition \_\_\_\_\_ GPS (Lat) (Long) \_\_\_\_\_

|                   |  |  |  |  |             |
|-------------------|--|--|--|--|-------------|
|                   | Piles  |  |  |  |             |
| Comment           | Two soil stockpiles were on location, one of which was marked "Topsoil Storage" and the other was unmarked. BMPs are adequate. |  |  |  |             |
| Corrective Action |  |  |  |  | Date: _____ |

**Spill/Remediation:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                            | URL   |
|--------------|--|---|
| 717100094    | ECMC Photo Log - Highum, Norden, Clark | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6895103">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6895103</a> |