

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2025

Submitted Date:

01/28/2025

Document Number:

699700459

**FIELD INSPECTION FORM**

Loc ID 322319 Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 51130  
Name of Operator: LOCIN OIL CORPORATION  
Address: 600 TRAVIS STREET SUITE 5050  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Frost, Joe	7137423642	jfrost@americanhelium.us	<a href="#">American Helium President</a>
Toews, Wesley J	9703195683	wtoews@blm.gov	<a href="#">BLM West Slope</a>
Cholas, Nick		nick.cholas@state.co.us	
Roberts, James		j75rober@blm.gov	<a href="#">BLM meeker</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111746	PIT				-	PRAIRIE CANYON 1-17	EI
210270	WELL	SI	02/01/2021	GW	045-06026	PRAIRIE CANYON FEDERAL 1-17	EI

**General Comment:**

[ECMC Environmental Inspection. Any corrective action\(s\) from previous inspections that have not been addressed are still applicable.](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: [Wildlife protections devices not adequate.](#)

Corrective Action: [Install or repair wildlife protection equipment.](#)

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Flow Line

#

Comment: [Valves not locked and tagged out.](#)

Corrective Action: [Maintain active and inactive flowlines and crude oil transfer lines to meet rule 1102.i.](#)

Date: \_\_\_\_\_

Type: Flow Line

#

Comment: [Flowlines or crude oil transfer lines not maintained to prevent failures or leakage at the wellhead.](#)

Corrective Action: [Maintain active and inactive flowlines and crude oil transfer lines to meet rule 1102.i.](#)

Date: \_\_\_\_\_

**Venting:**

Yes/No

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 111746 Type: PIT API Number: - Status:  Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 210270 Type: WELL API Number: 045-06026 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Based on COGIS and Google Earth Aerials, Pit Facility ID 111746 is acting as the secondary containment for the 70 bbl open top produced water steel AST.	heilj	01/29/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700461	20250122 Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6895193">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6895193</a>