

Inspection Photos

ID: 412152

Operator: **MULL DRILLING COMPANY INC**

Inspection Date: 1/28/2025

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. There is oil leaking out of the truck load out at the MUSF #2 TB.



Inspection Photos



Photo 2. Facing toward the adjacent pasture south of the tank battery. There is insulation debris scattered in this pasture that needs to be cleaned up.



Inspection Photos



Photo 3. Facing east at the south side of the location. There is also a piece of tin shown at red arrow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. The observed tin and insulation have blown off this tank.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID:412152 | Date: 1/28/2025