

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/31/2024

Submitted Date:

12/31/2024

Document Number:

716300401**FIELD INSPECTION FORM**Loc ID 307604 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217886	WELL	PR	05/13/2014	CBM	071-06665	LORENCITO 2-8-34-66	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
Produced Water	Tank	>= 5 bbls		
Comment:	PHOTO 5: PRODUCED WATER TANK IS OVERFLOWING AND SECONDARY CONTAINMENT IS ALMOST FULL (SPOKE WITH ED ROMERO BY TEXT MESSAGE OPERATOR IS SENDING LEASE OPERATOR AND WATER TRUCK).			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 01/01/2025

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type			corrective date
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		37.103836,-104.798814

Comment:					
Corrective Action:					Date: <input type="text"/>
<u>Paint</u>					
Condition	<input type="text"/>	<input type="text"/>			
Other (Content)	<input type="text"/>				<input type="text"/>
Other (Capacity)	210 BBL				<input type="text"/>
Other (Type)	<input type="text"/>				<input type="text"/>
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	<input type="text"/>
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	<input type="text"/>
Comment:	<input type="text"/>				<input type="text"/>
Corrective Action:	<input type="text"/>				Date: <input type="text"/>
<u>Venting:</u>					
Yes/No	NO				<input type="text"/>
Comment:	<input type="text"/>				<input type="text"/>
Corrective Action:	<input type="text"/>				Date: <input type="text"/>
<u>Flaring:</u>					
Type	<input type="text"/>				<input type="text"/>
Comment:	<input type="text"/>				<input type="text"/>
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

Inspected Facilities									
Facility ID:	217886	Type:	WELL	API Number:	071-06665	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	10/08/2015		Annual Brhd Completed?						
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:	FORM 4 ON FILE								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 261257Lat: 37.104000Long: -104.798727Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action: Date:

Permit:	Facility ID	Permit Num	Expiration Date
	261278	852033	
	261257	852016	

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716300402	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6897544