

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/23/2025

Submitted Date:

01/23/2025

Document Number:

718000022**FIELD INSPECTION FORM**Loc ID 439215 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10261Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLCAddress: 730 17TH ST STE 500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rogers, Brad		brogers@bayswater.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439207	WELL	PA	06/13/2024	OW	123-40353	WAAG 9	EI
439210	WELL	PA	10/24/2023	OW	123-40356	WAAG 6	EI
439211	WELL	PA	06/13/2024	OW	123-40357	WAAG 8	EI
439214	WELL	PA	06/14/2024	OW	123-40360	WAAG 11	EI
439216	WELL	PA	06/14/2024	OW	123-40361	WAAG 12	EI
439217	WELL	PA	06/13/2024	OW	123-40362	WAAG 10	EI
439219	WELL	PA	12/27/2023	OW	123-40364	WAAG 7	EI
488362	SPILL OR RELEASE	CL	10/11/2024		-	WAAG 9 Historic Release	EI

General Comment:[ECMC Environmental Inspection for Remediation Project 34906 for well P&A and flowline abandonment](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

6

Comment:

Corrective Action:

Date:

Type: Bradenhead

6

Comment:

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities				
Facility ID: 439207	Type: WELL	API Number: 123-40353	Status: PA	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 439210	Type: WELL	API Number: 123-40356	Status: PA	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 439211	Type: WELL	API Number: 123-40357	Status: PA	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 439214	Type: WELL	API Number: 123-40360	Status: PA	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 439216	Type: WELL	API Number: 123-40361	Status: PA	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 439217	Type: WELL	API Number: 123-40362	Status: PA	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 439219	Type: WELL	API Number: 123-40364	Status: PA	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 488362	Type: SPILL OR	API Number: -	Status: CL	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Environmental

Spill/Remediation:

Comment:

ECMC Environmental Inspection of Remediation Project 34906 for well P&A and flowline abandonment, and followup to reported historical Release at WAAG 9 well. Operator reported historical Release documenting TPH impacts in the well excavation. All well excavations onsite are currently open. Flowlines appear to remain in place.

Operator has submitted soil sample analytical results for 5 of 7 wells: Waag 8,9,10,11,12. P&A wells Waag 6 and Waag 7 have apparently not been assessed. Flowlines have not been assessed.

Operator submitted a Supplemental Form 27, Document #404058882 requesting to further extend remediation excavation and assessment schedule. However no justification has been provided for the delay in the excavation at the Waag Middle pad or the Waag North pad (Remediation 34900). Form 27 Document #404058882 was denied.

Corrective Action:

Operator shall commence execution of the approved Form 27 Site Investigation and Remediation Workplan as approved on Document #s 403730354, 403833066 and 403955599.

Date:

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404068403	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6887853
718000024	Waag Middle Photos 1-23-2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6887830