


**Inspection/Audit Photos**  
**Location Name: QB Energy DUNN 9-4 (C9E) Pad**  
**Location ID: 334841**



**Photo # 1709 From entrance to location**



**Photo # 1710 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy DUNN 9-4 (C9E) Pad**  
**Location ID: 334841**



**Photo # 1711 Location**



**Photo # 1712 Location**



**Inspection/Audit Photos**  
**Location Name: QB Energy DUNN 9-4 (C9E) Pad**  
**Location ID: 334841**



**Photo # 1713 Location**



**Photo # 1714 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy DUNN 9-4 (C9E) Pad**  
**Location ID: 334841**



**Photo # 1715 Location**



**Photo # 1716 Location**



**Inspection/Audit Photos**  
**Location Name: QB Energy DUNN 9-4 (C9E) Pad**  
**Location ID: 334841**



**Photo # 1717 Location**




**Photo # 1718 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy DUNN 9-4 (C9E) Pad**  
**Location ID: 334841**




**Photo # 1719 Location**




**Photo # 1720 Location**



**Inspection/Audit Photos**  
**Location Name: QB Energy DUNN 9-4 (C9E) Pad**  
**Location ID: 334841**



**Photo # 1721 Location**



**Photo # 1722 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy DUNN 9-4 (C9E) Pad**  
**Location ID: 334841**



**Photo # 1723 Tanks lack secondary containment/failure to comply with COA**



**Photo # 1724 Tanks lack secondary containment/failure to comply with COA**



**Inspection/Audit Photos**  
**Location Name: QB Energy DUNN 9-4 (C9E) Pad**  
**Location ID: 334841**



**Photo # 1725 Tanks lack secondary containment/failure to comply with COA**