

Inspection Photos

API: 017-06410

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 1/28/2025

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and vehicles shall not drive outside of the access road boundary. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06410 | Date: 1/28/2025

Inspection Photos




Photo 2. Facing southwest toward the wellsite.



Inspection Photos



Photo 3. Facing west toward the wellsite. There was a leak at the wellhead which appears to have flowed to the east side of the location. There is white and blackened soils which appears to be condensate from the well.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06410 | Date: 1/28/2025

Inspection Photos




Photo 4. Facing northwest toward the wellsite. There was a leak at the wellhead which appears to have flowed to the east side of the location. There is white and blackened soils which appears to be condensate from the well.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06410 | Date: 1/28/2025

Inspection Photos



Photo 5. There is a black barrel that blew off the location.

