

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2025

Submitted Date:

01/31/2025

Document Number:

715201637**FIELD INSPECTION FORM**Loc ID 321892 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 992 S 4TH AVE SUITE 100-461City: BRIGHTON State: CO Zip: 80601**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	
Reed, Shawn	303-562-6530	shawn@sreedconsulting.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208414	WELL	PR	06/01/2020	OW	017-07349	UPRC 1-35	PR

General Comment:[SE Compliance Specialist Brian Welsh](#) conducted a routine field inspection of the well location and equipment

Location

Lease Road:			
Type	Access		
comment:	Partially elevated gravel road along farm ground with a cattle guard		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at unit. Update to current operator		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	03/02/2025
Type	BATTERY		
Comment:	Lease sign at tanks needs updated to current operator		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	03/02/2025
Type	TANK LABELS/PLACARDS		
Comment:	Install tank labels		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	03/02/2025

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Wire panels around wellhead and unit		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Wire panels around tank battery		
Corrective Action:		Date:	

Equipment:			corrective date
Type: FWKO	# 1		
Comment:	FWKO west side of tank battery		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Type: Pump Jack	# 1	
Comment: CMI 320		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: Electric motor		
Corrective Action:		Date:
Type: Ancillary equipment	# 4	
Comment: Control panel, cathodic rectifier, electric panel, chemical tank w/containment		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	500 BBLs	FIBERGLASS AST		38.879550,-102.300150
Comment: Overflow for production water tank on west side of tank battery has been removed					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	200 BBLs	FIBERGLASS AST		38.879550,-102.300150
Comment: Water tank on west side of gun barrel tank has been removed					
Corrective Action:			Date:		

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0	400 BBLs	FIBERGLASS AST		38.879550,-102.300150

Comment:	Gun barrel on west side of production tanks has been removed					
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	FIBERGLASS AST		38.879550,-102.300150	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No					
Comment:					
Corrective Action:					Date:

Flaring:

Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	208414	Type:	WELL	API Number:	017-07349	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Tank battery is 350' south of wellhead								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201638	Puming unit	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900200
715201639	tank battery	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900201