

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/31/2025

Submitted Date:

01/31/2025

Document Number:

696307186

**FIELD INSPECTION FORM**

Loc ID: 410058 Inspector Name: PETRIE, ERICA On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10670  
Name of Operator: BISON IV OPERATING LLC  
Address: 518 17TH STREET SUITE 1800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Buck, Paul	303-882-5868	pbuck@bisonog.com	ALL INSPECTIONS
Garza, Tarah	970-514-3581	tgarza@bisonog.com	Environmental Compliance Specialist
Milne, Rachael	720-370-8580	rmilne@bisonog.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301750	WELL	SI	04/01/2023	GW	123-30089	FABRIZIUS 33-12	SI

**General Comment:**

This is a Well Site Field Compliance Audit

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	Livestock Panels		
Corrective Action:		Date:	

**Equipment:**

Type	Area	Volume			corrective date
Type: Bradenhead		# 1			
Comment:	Appears to be plumbed to surface				
Corrective Action:				Date:	
Type: Pump Jack		# 1			
Comment:					
Corrective Action:				Date:	
Type: Prime Mover		# 1			
Comment:	Gas Engine				
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 301750 Type: WELL API Number: 123-30089 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI - Since 04.01.2023  
Form 05B - 404066336 dated 01.22.2025 - Inactive well recently acquired - under  
evaluation for workover and RTP

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<a href="#">Routine Field Compliance Audit</a>	petrie	01/31/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696307187	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900704">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900704</a>