

Inspection/Audit Photos
Location: QB Energy Puckett/697-26A
Location ID: 416157
Date: 01/27/2025



Photo # 3524 Entrance to location




Photo # 3562 Location

Inspection/Audit Photos
Location: QB Energy Puckett/697-26A
Location ID: 416157
Date: 01/27/2025



Photo # 3525 Location



Photo # 3540 Location

Inspection/Audit Photos
Location: QB Energy Puckett/697-26A
Location ID: 416157
Date: 01/27/2025



Photo # 3545 Location



Photo # 3561 Location

Inspection/Audit Photos
Location: QB Energy Puckett/697-26A
Location ID: 416157
Date: 01/27/2025



Photo # 3592 SE corner of location



Photo # 3593 SW corner of location

Inspection/Audit Photos
Location: QB Energy Puckett/697-26A
Location ID: 416157
Date: 01/27/2025



Photo # 3594 NW corner of location



Photo # 3595 NE corner of location

Inspection/Audit Photos
Location: QB Energy Puckett/697-26A
Location ID: 416157
Date: 01/27/2025



Photo # 3549 Unused equipment



Photo # 3575 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos
Location: QB Energy Puckett/697-26A
Location ID: 416157
Date: 01/27/2025



Photo # 3577 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3578 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos
Location: QB Energy Puckett/697-26A
Location ID: 416157
Date: 01/27/2025



Photo # 3588 Wildlife hazard



Photo # 3579 Unused hose

Inspection/Audit Photos
Location: QB Energy Puckett/697-26A
Location ID: 416157
Date: 01/27/2025



Photo # 3580 Unused hose



Photo # 3581 Empty chemical containers

Inspection/Audit Photos
Location: QB Energy Puckett/697-26A
Location ID: 416157
Date: 01/27/2025



Photo # 3591 Containment showing signs of disrepair



Photo # 3598 Debris

