

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Photo # 2822 From entrance to location




Photo # 2823 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Photo # 2824 Location



Photo # 2825 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Photo # 2826 Location



Photo # 2827 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Photo # 2828 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 2829 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Photo # 2830 Cellar not properly covered/wildlife & personnel hazard



Photo # 2831 Wildlife egress board needs adjustment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Photo # 2832 Valve on the 2 inch line connecting the RIVER RANCH A4 well BH line to the sales line appears to be shut



Photo # 2833 Capacity on tank label illegible/not in compliance with CECMC rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC RIVER RANCH A Pad

Location #: 336014



Photo # 2834 One 300 bbl tank added to location - Unable to locate FORM 4 SUNDRY for this equipment/not in compliance with CECMC rules



Photo # 2835 One 300 bbl tank added to location - Unable to locate FORM 4 SUNDRY for this equipment/not in compliance with CECMC rules