

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 2921 From entrance to location




Photo # 2922 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 2923 Location



Photo # 2924 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 2925 Location



Photo # 2926 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Jan 30, 2025 at 12:57:29 PM  
CO

Photo # 2927 Location



Jan 30, 2025 at 12:59:20 PM  
CO

Photo # 2928 Location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



Photo # 2929 Location



Photo # 2930 Damaged hose/debris

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



**Photo # 2931 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 2932 PRV vent line does not comply with CECMC pressure safety device rules**



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC ROBINSON A Pad

Location #: 336015



**Photo # 2933 Hole in secondary containment liner/liner needs maintenance**



**Photo # 2934 Hole in secondary containment liner/liner needs maintenance**