

# Inspection Photos

API: 017-06629

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 1/28/2025

County: Cheyenne




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road has not been repaired.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06629 | Date: 1/28/2025



## Inspection Photos



**Photo 2.** Facing toward the wellhead. There are stained soils by the wellhead. Previous CA was not completed.





## Inspection Photos



**Photo 3.** View of oil stained soils at the wellhead.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos




**Photo 4.** There is a pile of oily rags at the south side of the location. This must be removed and properly disposed. Previous CA was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 5.** Facing toward the pumpjack. The engine has been replaced with an electric motor. It is unknown if oil saturated soils were cleaned up due to sand previously spread over this area.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06629 | Date: 1/28/2025



## Inspection Photos



**Photo 6.** Facing northwest toward the wellsite. The red arrow points to an oily rag that still remains.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 7.** The labeling on the barrels is faded and needs to be updated.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:017-06629 | Date: 1/28/2025