

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2025

Submitted Date:

01/28/2025

Document Number:

715201576

FIELD INSPECTION FORM

Loc ID 324872 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 37230
Name of Operator: HALDE OIL INC
Address: 46321 HWY 24
City: BURLINGTON State: CO Zip: 80807

Findings:

- 8 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Shalberg, Greg	719-688-3547	gregshalberg@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213346	WELL	SI	03/01/2024	GW	061-06708	MAYER 12-2 1	PA

General Comment:

[SE Compliance Specialist Brian Welsh conducted a Follow up Inspection from the P&A process](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
Date:	<input style="width: 100%;" type="text"/>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Compressor	# 1		
Comment:	Skid mounted gas powered booster compressor in metal shed		
Corrective Action:	Remove from location and begin final reclamation process	Date:	<u>02/18/2025</u>
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:	Remove from location and begin final reclamation process	Date:	<u>02/18/2025</u>
Type: Ancillary equipment	# 3		
Comment:	Gas scrubber, solar powered cathodic rectifier, telemetry equipment		
Corrective Action:	Remove from location and begin final reclamation process	Date:	<u>02/18/2025</u>
Type: Gas Meter Run	# 1		
Comment:	Meter shed on northwest corner of location		
Corrective Action:	Remove from location and begin final reclamation process	Date:	<u>02/18/2025</u>
Type: Pump Jack	# 1		
Comment:	SM-Cyclo 160		
Corrective Action:	Remove from location and begin final reclamation process	Date:	<u>02/18/2025</u>
Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:	Remove from location and begin final reclamation process	Date:	<u>02/18/2025</u>
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator on west side of metal shed		
Corrective Action:	Remove from location and begin final reclamation process	Date:	<u>02/18/2025</u>

Venting:			
Yes/No			

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 213346 Type: WELL API Number: 061-06708 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404073284	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6893946
715201630	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6893943