

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2025

Submitted Date:

01/28/2025

Document Number:

715501195**FIELD INSPECTION FORM**Loc ID 312863 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10407Name of Operator: ANTLER ENERGY LLCAddress: PO BOX 104City: BAGGS State: WY Zip: 82321**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Clay	(307) 380-7616	clay@antler-energy.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Enforcement, ECMC		dnr_cogccenforcement@state.co.us	
Hoak, Thomas	(720) 594-8372	thomas.hoak@state.co.us	Enforcement

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222661	WELL	PR	06/01/2015	GW	081-06021	FEDERAL-CHAMBERLIN 22-1	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday, 01/28/2025, Inspector Kirby Burchett, conducted a follow up field audit and inspection at Antler Energy LLC on the Federal-Chamberlin 22-1 well, Location #312863, in Moffat County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District with High Priority, NSO, Density, and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #715500863 on 10/24/24 and Insp. #715500160 on 6/4/24. The following Corrective Actions have not been resolved and original due dates remain:

1. Random debris.
2. Oily waste and stained soils.
3. Unlabeled lube tank on stand.
4. Equipment open to wildlife.
5. Production Reporting still out of compliance.

Refer to Inspection Photos for observed

While there during normal operations no additional compliance issues were observed.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Unlabeled tank on stand at pumping unit engine		
Corrective Action:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.	Date:	06/10/2024
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.	Date:	06/12/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	
Lube Oil	Pump Jack		
Comment:	Oily waste around engine. Base and around the edges. Oily waste needs to be removed. Not covered.		
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.		Date: 06/20/2024
Crude Oil	Tank		
Comment:	Several areas inside tank battery containment with oily waste and stained soil		
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.		Date: 06/20/2024
Crude Oil	WELLHEAD		
Comment:	Oily waste and stained soil.		
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.		Date: 06/20/2024

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment: Manufacturer 3 rail

Corrective Action:

Date:

Equipment:

corrective date

Type: Vertical Heater Treater

1

Comment: Burner on treater open to wildlife.

Corrective Action: All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats.

Date: 06/15/2024

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

5

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: Unlabeled lube tank in containment

Corrective Action:

Date:

Type: Bird Protectors

4

Comment:

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			

Inspected Facilities									
Facility ID:	222661	Type:	WELL	API Number:	081-06021	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	September 2024 Production Reported Review of production records indicate operator is still delinquent in submitting monthly operations reports in a timely manner. October 2024 Form 7 due December 15, 2024. November 2024 Form 7 due January 15, 2025.								
Corrective Action:	Operators will report all existing oil and gas Wells that are not Plugged and Abandoned on the Form 7, Operator's Monthly Report of Operations within 45 days after the end of each month. A Well will be reported every month from the month that it is spud until it has been reported for one month as abandoned.						Date:	11/24/2024	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		Limited Stormwater due to snow cover Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.				
Corrective Action:						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404073303	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6893982
715501196	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6893979