

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2025

Submitted Date:

01/28/2025

Document Number:

717100081

FIELD INSPECTION FORMLoc ID 475409 Inspector Name: Rollins, Grace On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
,		ECMCInspections@Oxy.com	All Inspections
Brown, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
487626	TANK BATTERY	AC	08/20/2024		-	Stromquist 14-21 Facility	EI

General Comment:**ECMC Environmental Field Inspection Report Summary**

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Site Name: Stormquist 14-21 Facility

Remediation Project #: 36866

Facility ID: 487626

Date of Inspection: 01/15/2025

Location is within or adjacent to:

- Bald Eagle Roost Site High Priority Habitat
- Frederick Municipality
- Crop Field

Current site conditions:

- Rutting was observed on the west side of the facility.
- Metal fencing surrounds all infrastructure on location.
- Production tanks are contained within a metal berm.
- Signage with emergency contact number is visible.
- NFPA placards are visible on production tanks.
- No environmental impacts were visible.

Location Construction

Location ID: 487626 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: Rutting was observed on the west side of the facility.

Corrective Action: Maintain required BMPs per Rule 1002.f.(2)C.

Date: 02/12/2025

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	487626	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation Project No. 36866 was created for decommissioning of the Stormquist 14-21 Facility. Decommissioning activities had not commenced at the time of inspection. No environmental impacts were visible. Quarterly reporting is required under Remediation Project No. 36866.

Corrective Action: _____

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404072087	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892880
717100082	ECMC Photo Log - Stormquist 14-21 Facility	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892870