

Final Reclamation and Stormwater Inspection

January 24, 2025

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 463813

Well Name: DADO #3-21

Inspection Document #: 718600230

Lincoln County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DADO #3-21
Location ID: 463813



Photo 1. Looking south down access road. Due to snow cover a full vegetative assessment could not be completed.



Photo 2. Looking southwest down access road toward well site.



Inspection Photos
Location Name: DADO #3-21
Location ID: 463813



Photo 3. The access road in front of the gate appears to have perennial vegetation established.



Photo 4. The location is fenced. Sign at entrance of location.



Inspection Photos
Location Name: DADO #3-21
Location ID: 463813



Photo 5. Looking east from well location. Due to snow cover a full vegetative assessment could not be completed.



Photo 6. Looking west from well location. See Photo 5 comments.

Inspection Photos
Location Name: DADO #3-21
Location ID: 463813



Photo 7. Google earth aerial image from 10/2024. Location appears to have reclamation work conducted.

