

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2025

Submitted Date:

01/29/2025

Document Number:

713601819

FIELD INSPECTION FORM

Loc ID 476137 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96730
Name of Operator: WILLIFORD ENERGY COMPANY
Address: 6060 AMERICAN PLAZA SUITE 760
City: TULSA State: OK Zip: 74135

Findings:

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Storts, Doug		pds@willifordenergy.com	
GROWNS LARRY		lgrowsns@willifordenergy.com	
Sanchez, Chris		chris.sanchez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476137	LOCATION	AC			-	RHOADES UNIT TUBING FLOWLINE 3213S48W	RI

General Comment:

This is a follow up inspection at the RHOADES UNIT Tank Battery Location #476137. See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	The tanks labels are missing and faded. No NFPA label on some of the tanks.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	09/21/2024

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	There have been three unused tanks removed since the previous inspection.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			
Crude Oil	Tank				
Comment:	There was oil stained soils around the tanks and shed that will need to be cleaned up. There is also oil stains along the flowline going to the heater treater. A form 19 has been submitted since the previous inspection. The form 19 document #403977660 requires multiple Conditions of Approval which have not been completed.				
Corrective Action:	Immediately Comply with form 19 document #403977660 COA's.			Date:	

In Containment: Yes

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Environmental

Spills/Releases:

Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: There has been a new spill that occurred at the Rhoades Unit Tank Battery. There was a leak at the heater treater that spilled hydrocarbon mist along the west side berm. It appears the leak flowed to the southeast corner of the location. There was also a condensate leak that occurred from the fiberglass tank and flowline shed. It appears this leak overtopped the berm at the southeast coner.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Report spill or release of E&P waste or produced fluids Remove free fluids and contact ECMC EPS staff per Rule 912.b.

Date: 01/30/2025

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404074462	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6895104
713601820	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6895100