

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/03/2025

Submitted Date:

02/05/2025

Document Number:

717300204**FIELD INSPECTION FORM**Loc ID 336298 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246778	WELL	SI	06/01/2022	GW	123-14575	SARCHET UPRR 42-23 3X	PA
283705	WELL	TA	03/03/2016	GW	123-23679	SARCHET 41-23	PA
336298	LOCATION	AC			-	SARCHET UPRR-63N66W 23SENE	EG

General Comment:ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 246778 Type: WELL API Number: 123-14575 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 283705 Type: WELL API Number: 123-23679 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 336298 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
As outlined on ECMC form 19 spill report Doc #404061406 received on 01/17/2025: While conducting wellhead plugging and abandonment and flowline removal activities at the Sarchet 8-23A wellhead, historically impacted soil was discovered at the wellhead. The volume of the release is unknown. The wellhead has been plugged and abandoned.	maclarej	02/05/2025
Wells are plugged and abandoned (Sarchet 41-23, 42-23 3X); ECMC form 42 notice of start of plugging operations doc #403905093 received on 08/29/2024. The facility/ tank battery has been decommissioned; tanks and equipment removed. ECMC form 42 notice of flowline abandonment completed doc #404031809 received 12/17/2024 (OL FL's removed). No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is in progress.	maclarej	02/05/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300209	Fenced excavation at PA well; view E to facility	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6906059
717300210	Excavation at decom facility/ battery; OOS GMR	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6906060