

Inspection Photos

API: 011-05055

Loc: 321208

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 2/4/2025

County: Prowers



Inspection Photos



Photo 1. Drone aerial photo facing northeast toward the GAS PROCESSING PLANT and Wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 2/4/2025

Inspection Photos



Photo 2. Drone aerial photo facing southwest toward the GAS PROCESSING PLANT and Wellsite.



Inspection Photos



Photo 3. Facing northeast toward the GAS PROCESSING PLANT and Wellsite.



Inspection Photos



Photo 4. Facing northeast at the location. There is various unused equipment, supplies and tanks stored at the location that will need to be removed. Previous CA has not been completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 2/4/2025

Inspection Photos



Photo 5. Facing northwest toward the GAS PROCESSING PLANT and Wellsite. There is various supplies and debris scattered throughout the location.



Inspection Photos



Photo 6. Facing northwest at the sheds and various equipment which are in disrepair. There is chemical barrels with no containment and various debris laying on the ground.



Inspection Photos



February 4, 2025
+38.203099,-103.141424
Bent County
ECMC

Photo 7. This blue barrel has leaked out oil onto the ground.



Inspection Photos




Photo 8&9. There are sheds in disrepair with large bird nests. Operator will need to consult with USFS and CPW regarding time restrictions and relocation of any migratory bird nests.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 321208 | Date: 2/4/2025

Inspection Photos



Photo 10. Facing northwest at the sheds and equipment which are in disrepair.



Inspection Photos



Photo 11. Facing southeast at the west side of the location. This shed and fence are in disrepair with supplies have fallen out of the dilapidated shed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 2/4/2025

Inspection Photos



Photo 12. There is panels, boards, and a blue barrel laying on the ground which has leaked out fluids onto the ground..



Inspection Photos



Photo 13. Facing northeast toward the well. The fence around the pumpjack is in disrepair and there is unused equipment stored near the well.



Inspection Photos



Photo 14. North side of the location facing east. There is various unused equipment stored on location that needs to be removed.



Inspection Photos



Photo 15. Facing southeast at the location. There are various unused equipment, wire, and debris stored on location that needs to be removed. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 2/4/2025

Inspection Photos



Photo 16. North side of the location facing east. There are unused tanks stored and various supplies scattered throughout the location.



Inspection Photos



Photo 17. Facing southwest at the location. There are hardened hydrocarbon impacts shown at red arrow.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 2/4/2025

Inspection Photos



Photo 18. Facing southwest at the location. The old tank was removed and anew one has been installed. It is unknown if impacts around the tank were cleaned up. There are two unused tanks stored on location at red arrow.



Inspection Photos



Photo 19. Facing northwest at the south side of the location. There is an open top fiberglass condensate tank with no wildlife or livestock protections. There are cattle tracks all around the tank indicating that cattle could be drinking out of this tank.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 2/4/2025

Inspection Photos



Photo 20. Facing toward the open top tank which has oil condensate inside the tank with no wildlife or livestock protection.



Inspection Photos



Photo 21. Facing northwest at the location. There is various pipe, supplies, and debris scattered throughout the location.

