

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/06/2025

Submitted Date:

02/05/2025

Document Number:

718200015

FIELD INSPECTION FORM

Loc ID: 328585 Inspector Name: Metz, Collin On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Robinson, Taylor		taylor.robinson@state.co.us	
Ochoa, Ariana		Ariana_Ochoa@oxy.com	Oxy Environmental
,		ECMCInspections@Oxy.com	All Inspections
Anderson, Laurel		laurel.anderson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
487149	SPILL OR RELEASE	CL	06/20/2024		-	Chadima 4-14/Christy Facility	EI

General Comment:

Environmental inspection was conducted on January 6, 2025, by ECMC Environmental Protection Specialists Laurel Anderson and Collin Metz, to determine progress on Spill ID #487149/Remediation #34426 at Chadima 4-14/Christy Facility. Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Incident information:

Operator: Kerr McGee
Location ID #328585 - HSR-CHADIMA-63N66W14NWNW
Spill Discovery Date: 6/19/2024
Days since spill discovery: 231 days (as 2/5/2025)
Last report: Form 27 Document #403934320 Received on 9/28/2024

Current Status:

- Weeds
- Signage references wellhead
- Orange construction fencing around flowline potholes does not encompass the entire hole.
- Excavation fencing is adequate
- Ice/saturated soil in base of the excavation
- Remedial excavation remains open.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type WEEDS

Comment: [See attached photo of weeds within the excavation.](#)

Corrective Action: [Comply with Rules 606.c. and 1003.f.](#)

Date: 02/19/2025

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: [Orange construction fencing around flowline potholes does not encompass the entire hole.](#)

Corrective Action: [Repair and maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by Rule 913.b\(5\)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended. the site was not attended at the time of the inspection.](#)

Date: 02/06/2025

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 487149 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718200016	Photo Documentation	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6906583